

2005

MC1

DC1

Dust Collector 1 (roof)

2,005.00

Employee labor cost: \$ 1,249.69 42 Hours

DC1 TOTAL COST: \$1,249.69

MXR1

Mixer 1 A&J 4000# Mixer

2,005.00

Employee labor cost: \$ 2,868.75 98 Hours

Total parts issued from Storeroom: \$	75.44	6 Items
---------------------------------------	-------	---------

MXR1 TOTAL COST: \$2,944.19

PK1A

IMPELLER PACKER 1A ON MC1

2,005.00

Employee labor cost: \$ 1,069.88 36 Hours

Total parts issued from Storeroom: \$	144.25	2 Items
---------------------------------------	--------	---------

PK1A TOTAL COST: \$1,214.13

PK1B

IMPELLER PACKER 1B ON MC1

2,005.00

Employee labor cost: \$ 612.98 20 Hours

Total parts issued from Storeroom: \$	56.18	1 Items
---------------------------------------	-------	---------

PK1B TOTAL COST: \$669.16

MC1 TOTAL COST: \$6,077.16 Cumulative yearly: \$98,200

MC2

DC2

Dust Collector 2 on MC2 (Roof)

2,005.00

Employee labor cost: \$ 24.38 1 Hours

DC2 TOTAL COST: \$24.38

MXR2

Mixer 2 on MC 2 A&J 4000#

2,005.00

Employee labor cost: \$ 1,256.25 42 Hours

Total parts issued from Storeroom: \$	620.00	2 Items
---------------------------------------	--------	---------

MXR2 TOTAL COST: \$1,876.25